Appendix - summary of proposed work to be undertaken

Element	General condition	Priority rating	Budget costing	Rationale for inclusion
1976/81 sections				
Floors	С	2	1,500	Health and Safety issue - reducing exposure to claims
Electrical				
Bonds to water pipes	С	1	5,000	To conform with electrical wiring regulations
Mechanical				
Investigate further condition of cold water	_			CPM undertaken Legionnella survey and commencing remedial work early 2012. This is a provision
pipework distribution system and provision	С	1	12,500	to cover any additional work identified that is not a Legionnella issue - for example investigation of
for any urgent remedial work				water system and replacement of corroded pipework
1077/1001				
1875/1904 sections			40.000	
Roof general	В	2	43,000	Allowance for upgrades to roof access - works currently being undertaken to upgrade
			40.000	general condition of roof covering(s)
Internal areas	В	2		Allowance for investigation & potential remedial works to cast iron frame to 1904 building
Ceilings	В	2	4,000	Allowance to replace rotten timber boarding at high level - Health & Safety issue
Electrical Items				
Denless ansanan ilinkta	Б	0	40.500	Allerman and a sum and those to be an annual and at the set of EDA
Replace emergency lights	В	2		Allowance made, expenditure to be as per recommendations of FRA
Replace dist. Boards	С	1		Allowance made, works to be as per recommendations following electrical inspections currently
Deplete lighting to underground duete	0	4		being undertaken
Replace lighting to underground ducts	С	1	5,000	Health and safety issue - lighting upgrade required.
Mechanical items				
Sprinkler systems	D	1	50,000	further investigation and improvement works to 1875 & 1904 sprinkler systems.
Upgrade to fan controls	С	2	26,000	Recommended if the ventilation systems are to remain as existing
New roof extract fans to 1904 building	С	2	100,000	Recommended if the ventilation systems are to remain as existing
Replace toilet extract fans	С	1		Environmental building regulations requirement
General				
Surveyor's report (Faithful & Gould) & PPPU fees			20,000	

sub-total 315,800

Allowance for professional fees @ 15% 47370 Allowance for prelims @10% 36317

Total: 399,487

Key:

General condition: A = Good, B = Satisfactory, C = Poor, D = very poor/life expired

Priority: Urgent 1 -4 long term maintenance