

Appendix C – Photographs and Figures



Figure 1 – Flooding in Leeds Road – Allerton Bywater August 2014




Figure 2 – Existing properties at risk and key site features – Westfields




Figure 3 – Proposed construction of drainage system - Westfields